

Reworking Samtec's Solder Ball Connectors

This document describes the recommended procedure for reworking (connector removal, site cleaning, and connector replacement) Samtec's solder ball connectors (including, but not limited to ADX6, APX6, and NVAX) using hot air rework equipment.

Equipment Used:

Air-Vac DRS27 BGA/SMT rework machine Air-Vac NT582LZ2326S hot air rework nozzle

Other Materials:

NVAM-DP-06-1-02.0-S-2 connector Alpha OM-338 Pb-free, no-clean solder paste Kester TSF-6522 no-clean rework flux Mini-stencil PCB thickness .062

Thermal Profiling

Prior to each process, a complete thermal profile study shall be completed. Thermocouples shall be placed directly beneath the center of the component as well as on the insulator body. The ideal process will replicate the temperature gradient and ramp rate as recommended by the solder paste manufacturer.




Figure 1. Thermocouple Placement

Process 1 - Connector Removal

 Place board to be reworked on hot air rework machine.




Figure 2. Board Placed on Rework Machine

- Align nozzle over component.
- Apply tacky flux to solder joints along each side of the connector.




Figure 3. Flux Application



Run connector removal heating program.




Figure 4. De-soldering Process - Nozzle in Down Position

Samtec Removal Program Settings*

Pre-heat board to 140°C

Bottom heater – 325°C

Pre-soak

- Z-axis hot gas heater 220°C, 85% flow
- Bottom heater 275°C for 30 seconds

Soak

- Z-axis hot gas heater 240°C, 85% flow
- Bottom heater 275°C for 45 seconds

Ramp

- Z-axis hot gas heater 255°C, 85% flow
- Bottom heater 275°C for 50 seconds

Reflow

- Z-axis hot gas heater 265°C, 85% flow
- Bottom heater 275°C for 50 seconds
- * Customer settings may be different
- After (removal) heating program is complete, quickly remove connector as nozzle rises.




Figure 5. Connector Removal

Process 2 - Site Cleaning

Apply tacky flux to area to be site-cleaned.




Figure 6. Flux Application

- Run site cleaning thermal program.
 (Once site-cleaning nozzle is lowered, manually adjust table location until all pads have been cleaned, resulting in a flat surface with a thin coating of solder.)
- If a site cleaning feature is not available, a manual site cleaning process is required.

Samtec Site Clean Program Settings*

Pre-heat board to 120°C

Bottom heater – 300°C

Site Clean

- Z-axis hot gas heater 425°C, 55% flow
- Bottom heater 270°C
- * Customer settings may be different




Figure 7. Site-Cleaning



Process 3 - Connector Replacement

 Apply solder paste to pads using the Samtec recommended stencil aperture design using either a stencil, mini-stencil, or solder jet printer.




Figure 8. Solder Paste Application (Mini-Stencil)

 Place printed PCB on rework machine and populate component.




Figure 9. Populated PCB

Run connector replacement thermal program.

Samtec Soldering Program Settings*

Pre-heat board to 140°C

Bottom heater – 325°C

Pre-soak

- Z-axis hot gas heater 220°C, 85% flow
- Bottom heater 275°C for 30 seconds

Soak

- Z-axis hot gas heater 240°C, 85% flow
- Bottom heater 275°C for 45 seconds

Ramp

- Z-axis hot gas heater 255°C, 85% flow
- Bottom heater 275°C for 50 seconds

Reflow

- Z-axis hot gas heater 265°C, 85% flow
- Bottom heater 275°C for 50 seconds
- * Customer settings may be different




Figure 10. Soldering Process - Nozzle in Down Position

For more information regarding reworking Samtec connectors, please contact Samtec's Interconnect Processing Group at ipg@samtec.com.

For more information on the hot air rework equipment/nozzles used, please contact:

Air-Vac Engineering 30 Progress Ave., Seymour, CT 06483 Telephone: 203-888-9900