









CRITICAL DIMENSION INSPECTION INSTRUCTION TABLE		
ASSEMBLY OPERATION	IN-PROCESS INSPECTION	
FILL C-177-01-XXX	C1, C4, C5, C6, C14, C18, C25	
FILL IM-1G18-01-2-XXX	C2, C9, C11, C15, C29	F
FILL C-178-02-XXX	C4, C5, C6, C8, C16, C24, C26	
FILL WT-16-XXX-T	C3, C7, C10, C13, C17, C27, C28	
APPLY K-DOT	C22, C23	
FINAL ASSEMBLY	C1, C4, C5, C6, C8, C9	

	CPC FREQUENCY THIS SHEET	PROPRIETARY NOTE THIS DOCUMENT CONTAINS INFORMATION CONFIDENTIAL AND PROPRIETARY TO SAMTEC, INC, AND SHALL NOT BE REPRODUCED OR TRANSFERRED TO OTHER DOCUMENTS OR DISCLOSED TO OTHERS OR USED TOR ANY PURPOSE OTHER THAN THAT WHICH IT WAS OBTAINED WITHOUT THE EXPRESSED WRITTEN CONSENT OF SAMTEC, INC.	520 PARK EAST BLVD, NEW ALBANY, IN 47150 PHONE: 812-944-6733 FAX: 812-948-5047 e-Mail info@SAMTEC.com code 55322
	B C1, C20	DO NOT SCALE DRAWING	DESCRIPTION: .50mm DOUBLE ROW RIGHT ANGLE SOCKET STRIP
0	C	SHEET SCALE: 2:1	DWG. NO. QSH-XXX-XX-X-D-RA-XXX
1			BY: DUKES Z 01/31/2010 SHEET 5 OF 6



